

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent Number: 7,161,440
Issue Date: January 9, 2007
Name of Patentee: David Meltzer
Application No.: 10/733,143
Filing Date: December 11, 2003
Confirmation No.: 7388
Title of Invention: Temperature Compensation Circuit

**REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT
FOR PTO MISTAKE (37 CFR §1.322(a))**

Sir:

It is noted that an error appears or errors appear in this patent of a clerical, typographical or minor nature or character, as more fully described below, due to a mistake by the U.S. Patent and Trademark Office.

Attached hereto is Form PTO-1050.

The exact page(s) and line number(s) where the error(s) occur in the patent are:

Column 20

Line 33, please change "summing output node" to --summing node--.

Column 23

Line 33, please change "said output third lead" to --said third lead--.

Patentee's undersigned attorney may be reached at the telephone number listed below. All correspondence should continue to be directed to our address listed below.

Respectfully submitted,

/Rosalio Haro/
Rosalio Haro
Registration No. 42,633

Please address all correspondence to:
Epson Research and Development, Inc.
2580 Orchard Parkway, Suite 225
San Jose, CA 95131
Customer No. 20178
Telephone: (408) 952-6131
Facsimile: (408) 954-9058

Date: March 18, 2008

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO.: 7,161,440
APPLICATION NO.: 10/733,143
ISSUE DATE: January 9, 2007
INVENTOR(S): David Meltzer

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 20

Line 33, please change "summing output node" to --summing node--.

Column 23

Line 33, please change "said output third lead" to --said third lead--.

MAILING ADDRESS OF SENDER:
Epson Research and Development, Inc.
Intellectual Property Department
2580 Orchard Parkway, Suite 225
San Jose, CA 95131

FORM PTO 1050